Table L1
 Cumulative Statistics on Exceedances

Parameters	Level of Exceedance	Total No. recorded in this reporting month	Total No. recorded since project commencement
1-hr TSP	Action	2	30
	Limit	0	2
24-hr TSP	Action	0	5
	Limit	0	1
Water Quality	Action	0	6
	Limit	0	1
Impact Dolphin	Action	0	7
Monitoring	Limit	0	0

Table L2 Cumulative Statistics on Complaints, Notifications of Summons and Successful Prosecutions

Reporting Period	Cumulative Statistics		
_	Complaints	Notifications of	Successful
		Summons	Prosecutions
This Reporting Month (December 2014)	0	0	0
Total No. received since project commencement	4	0	0

Email message

Environmental Resources Management

To ENVIRON - Hong Kong, Limited (ENPO)

16/F Berkshire House, 25 Westlands Road Quarry Bay, Hong Kong

From ERM- Hong Kong, Limited

Quarry Bay, Hong Kong Telephone: (852) 2271 3113 Facsimile: (852) 2723 5660 E-mail: jovy.tam@erm.com

Ref/Project number Contract No. HY/2012/08 Tuen Mun-Chek Lap

Kok Link-Northern Connection Sub-sea Tunnel

Section

Subject Notification of Exceedance for Air Quality

**Impact Monitoring** 

Date 12 December 2014



Dear Sir or Madam,

Please find attached the Notification of Exceedance (NOE) of the following Log no.:

0212330\_2December2014\_1hrTSP\_Station ASR5

A total of one Action Level Exceedance was recorded on 2 December 2014.

Regards,

Mr Jovy Tam

**Environmental Team Leader** 

#### **CONFIDENTIALITY NOTICE**

This facsimile transmission is intended only for the use of the addressee and is confidential. If you are not the addressee it may be unlawful for you to read, copy, distribute, disclose or otherwise use the information in this facsimile. If you are not the intended recipient, please telephone or fax us.

#### **ERM-Hong Kong, Limited**




# CONTRACT NO. HY/2012/08 TUEN MUN - CHEK LAP KOK LINK NORTHERN CONNECTION SUB-SEA TUNNEL SECTION

## Air Quality Impact Monitoring Notification of Exceedance

Log No.	0212330_2December2014_1hrTSP_Station ASR5		
	[Total No. of Exceedances = 1]		
Date	2 December 2014 (Measured)		
	11 December 2014 (Laboratory results received by ERM)		
Monitoring Station	ASR1, ASR5, ASR6, ASR10 and AQMS1		
Parameter(s) with	1.1TCD		
Exceedance(s)	1-hr TSP		
Action Levels	1-hr TSP (μg/m³)	ASR5 = 340	
	24-hr TSP (μg/m³)	ASR5 = 238	
Limit Levels	1-hr TSP (μg/m³)	500	
	24-hr TSP (μg/m³)	260	
Measured Levels	Action Level Exceedance for 1-hr TSP is observed at ASR5 (346 μg/m³) during 1510 - 1610 hrs.		
Works Undertaken (at	On 2 December 2014, Excavation Works for launching shaft were carried out at Reclamation Works		
the time of monitoring	Area Portion N-A; Land Bored Piling Works at Reclamation Works Area Portion N-A and Surcharge		
event)	Set Up at Reclamation Works Area Portions N-B and N-C.		


#### Possible Reason for The exceedance(s) are unlikely to be due to the Project, in view of the following: **Action or Limit Level** Considering the relatively higher levels of 1-hour TSP between 1500 and 1700 hrs at most Exceedance(s) monitoring stations, it is probably unlikely that the level of land-based construction works under this Contract can cause increase in 1-hour TSP of this magnitude and scale. It is considered that the observed exceedances for 1-hour TSP at ASR5 may represent sporadic event associated with traffic emissions and anthropogenic activities during afternoon rush hour at River Trade Terminal. According to the construction information provided by the Contractor, the majority of construction works on 2 December 2014 were Excavation Works for launching shaft at Reclamation Works Area Portion N-A; Land Bored Piling Works at Reclamation Works Area Portion N-A and Surcharge Set Up at Reclamation Works Area Portions N-B and N-C. During the period of the land-based construction works, the Contractor has implemented the required mitigation measures as per the EP, approved EIA and Updated EM&A Manual (e.g. water spraying by water trucks on exposed soil within the Project site and associated work areas; use of wheel washing facilities; hydro-seeding of area where works have been Whilst exceedances of Action Level were observed at ASR5, the 24-hr TSP level at the monitoring station (ASR1 = $127 \mu g/m^3$ ) on 2 December 2014 were in compliance with the Action and Limit Levels. Same level and extent of construction works were carried out at the same works area on 29th November and 5th December whilst no exceedance was recorded. With reference to the recorded wind direction (ranged between 34° and 65°, blowing from a North-Easterly direction) during the period of the observed 1-hr TSP exceedances, Station ASR5 is located upstream to the land-based construction activities at the Reclamation Works Area, thus the observed exceedance should not be affected by the dust, if any, generated by the construction activities under this Contract. As stated in the EIA report (Section 4.2.3), the background TSP level of Tuen Mun is higher than the other region of Hong Kong, thus the exceedances may be also contributed cumulatively by the other construction works / traffic within the Tuen Mun Area rather than causing by the construction works of the Project. Actions Taken / To Be Based on the record of subsequent weekly site inspection on 3 December 2014, no dust nuisance was Taken recorded at the Reclamation Works Area and activities conducted in this Contract's work has strictly followed the requirements stated in the EP (EP-354/2009/B) (see photo records on Annex A). In addition, the Contractor has implemented the required mitigation measures as per the EP, approved EIA and Updated EM&A Manual (e.g. watering at least 12 times per day on all exposed soil within the Project site and associated work areas; use of wheel washing facilities; hydro-seeding of area where works have been completed) throughout the construction period, no additional mitigation is deemed necessary. The Enhanced TSP Monitoring has commenced on 24 October 2014, the ET will monitor for future trends in exceedances. Remarks The monitoring results and the locations of air quality monitoring stations are attached.





### Annex A Photo Records taken during Weekly Site Inspection

\*Note: Photos taken on 3/12/2014



Hydro-seeding of area where works have been completed. (Reclamation Works Area)

Email message

Environmental Resources Management

To ENVIRON - Hong Kong, Limited (ENPO)

16/F Berkshire House, 25 Westlands Road Quarry Bay, Hong Kong

From ERM- Hong Kong, Limited

Quarry Bay, Hong Kong Telephone: (852) 2271 3113 Facsimile: (852) 2723 5660 E-mail: jovy.tam@erm.com

Ref/Project number Contract No. HY/2012/08 Tuen Mun-Chek Lap

Kok Link-Northern Connection Sub-sea Tunnel

Section

Subject Notification of Exceedance for Air Quality

**Impact Monitoring** 

Date 29 December 2014



Dear Sir or Madam,

Please find attached the Notification of Exceedance (NOE) of the following Log no.:

0212330\_17December2014\_1hrTSP\_Station AQMS1

A total of one Action Level Exceedance was recorded on 17 December 2014.

Regards,

Mr Jovy Tam

**Environmental Team Leader** 

#### **CONFIDENTIALITY NOTICE**

This facsimile transmission is intended only for the use of the addressee and is confidential. If you are not the addressee it may be unlawful for you to read, copy, distribute, disclose or otherwise use the information in this facsimile. If you are not the intended recipient, please telephone or fax us.

#### **ERM-Hong Kong, Limited**




# CONTRACT NO. HY/2012/08 TUEN MUN - CHEK LAP KOK LINK NORTHERN CONNECTION SUB-SEA TUNNEL SECTION

## Air Quality Impact Monitoring Notification of Exceedance

Log No.	0212330_17December2014_1hrTSP_Station AQMS1		
	[Total No. of Exceedances = 1]		
Date	17 December 2014 (Measured)		
	24 December 2014 (Laboratory results received by ERM)		
Monitoring Station	A	SR1, ASR5, ASR6, ASR10 and AQMS1	
Parameter(s) with Exceedance(s)	1-hr TSP		
Action Levels	1-hr TSP ( $\mu g/m^3$ )	AQMS1 = 335	
	24-hr TSP (μg/m³)	AQMS1 = 213	
Limit Levels	1-hr TSP (μg/m³)	500	
	24-hr TSP (μg/m³)	260	
Measured Levels	Action Level Exceedance for 1-h	r TSP is observed at AQMS1 (348 μg/m³) during 1444 - 1544 hrs.	
Works Undertaken (at	On 17 December 2014, Land Bor	ed Piling Works were carried out at Reclamation Works Area	
the time of monitoring		Up at Reclamation Works Area Portions N-B and N-C.	
event)			
Possible Reason for	The exceedance(s) are unlikely to be due to the Project, in view of the following:		
Action or Limit Level	According to the construction information provided by the Contractor, the majority of		
Exceedance(s)	construction works on 17 December 2014 were Land Bored Piling Works at Reclamation		
	Works Area Portion N-A and Surcharge Set Up at Reclamation Works Area Portions N-B and		
	N-C. During the period of the land-based construction works, the Contractor has		
	implemented the required mitigation measures as per the EP, approved EIA and Updated		
	EM&A Manual (e.g. water spraying by water trucks on exposed soil within the Project site		
	and associated work areas; use of wheel washing facilities; hydro-seeding of area where		
	works have been completed).		
	_	ction Level were observed at AQMS1, the 24-hr TSP level at the	
	monitoring station (AQMS1 = $155 \mu g/m^3$ ) on 17 December 2014 were in compliance with the Action and Limit Levels.		
	Same level and extent of	construction works were carried out at the same works area on 14th	
	December and 20th December whilst no exceedance was recorded. It is thus considered that		
	the observed exceedances for 1-hour TSP at AQMS1 may represent sporadic event associated		
	with traffic emissions and anthropogenic activities during afternoon rush hour at Lung Mun		
	Road.		
	With reference to the reco	orded wind direction (ranged between 44° and 60°, blowing from a	
		and wind speed (ranged from 2.7 to 5.4 m/s) during the period of	
		ceedances, Station AQMS1 is located upstream to the land-based	
		the Reclamation Works Area, thus the observed exceedance should	
		st, if any, generated by the construction activities under this	
	Contract.	, , , , , , , , , , , , , , , , , , ,	
		ort (Section 4.2.3), the background TSP level of Tuen Mun is higher	
	-	Hong Kong, thus the exceedances may be also contributed	
		r construction works / traffic within the Tuen Mun Area rather than	
	causing by the constructi		
	causing by the constituen	on words of the Froject	

Actions Taken/To Be	Based on the record of weekly site inspection on 17 December 2014, no dust nuisance was recorded	
Taken	at the Reclamation Works Area and activities conducted in this Contract's work has strictly follow	
	the requirements stated in the EP (EP-354/2009/C) (see photo records on <i>Annex A</i> ). In addition,	
	the Contractor has implemented the required mitigation measures as per the EP, approved EIA and	
	Updated EM&A Manual (e.g. use of water truck on exposed soil within the Project site and	
	associated work areas; use of wheel washing facilities; hydro-seeding of area where works have	
	been completed) throughout the construction period, no additional mitigation is deemed necessary.	
	The Enhanced TSP Monitoring has commenced on 24 October 2014, the ET will monitor for future	
	trends in exceedances.	
Remarks	The monitoring results and the locations of air quality monitoring stations are attached.	





### Annex A Photo Records taken during Weekly Site Inspection

\*Note: Photos taken on 17/12/2014



Hydro-seeding of area where works have been completed. (Reclamation Works Area)



Use of water truck on exposed soil within the Project site and associated work areas. (Reclamation Works Area)