


Air Quality Monitoring Data

Project	Works	Date (yyyy-mm-dd)	Station	Time	Parameter	Results	Unit
HKLR	HY/2011/03	2022-02-05	AMS5	15:25	1-hr TSP	31	µg/m ³
HKLR	HY/2011/03	2022-02-05	AMS5	16:25	1-hr TSP	56	µg/m ³
HKLR	HY/2011/03	2022-02-05	AMS5	17:25	1-hr TSP	62	µg/m ³
HKLR	HY/2011/03	2022-02-11	AMS5	09:06	1-hr TSP	23	µg/m ³
HKLR	HY/2011/03	2022-02-11	AMS5	10:06	1-hr TSP	25	µg/m ³
HKLR	HY/2011/03	2022-02-11	AMS5	11:06	1-hr TSP	40	µg/m ³
HKLR	HY/2011/03	2022-02-16	AMS5	09:00	1-hr TSP	44	µg/m ³
HKLR	HY/2011/03	2022-02-16	AMS5	10:00	1-hr TSP	43	µg/m ³
HKLR	HY/2011/03	2022-02-16	AMS5	11:00	1-hr TSP	45	µg/m ³
HKLR	HY/2011/03	2022-02-22	AMS5	13:00	1-hr TSP	20	µg/m ³
HKLR	HY/2011/03	2022-02-22	AMS5	14:00	1-hr TSP	29	µg/m ³
HKLR	HY/2011/03	2022-02-22	AMS5	15:00	1-hr TSP	26	µg/m ³
HKLR	HY/2011/03	2022-02-28	AMS5	09:07	1-hr TSP	28	µg/m ³
HKLR	HY/2011/03	2022-02-28	AMS5	10:07	1-hr TSP	26	µg/m ³
HKLR	HY/2011/03	2022-02-28	AMS5	11:07	1-hr TSP	25	µg/m ³
HKLR	HY/2011/03	2022-02-04	AMS5	08:00	24-hr TSP	23	µg/m ³
HKLR	HY/2011/03	2022-02-10	AMS5	08:00	24-hr TSP	55	µg/m ³
HKLR	HY/2011/03	2022-02-15	AMS5	08:00	24-hr TSP	55	µg/m ³
HKLR	HY/2011/03	2022-02-21	AMS5	08:00	24-hr TSP	8	µg/m ³
HKLR	HY/2011/03	2022-02-25	AMS5	08:00	24-hr TSP	41	µg/m ³


Remarks:

1) The existing air quality monitoring location AMS6 - Dragonair / CNAC (Group) Building (HKIA) was handed over to Airport Authority Hong Kong on 31 March 2021. 1hr and 24 hr air quality monitoring at AMS6 was temporarily suspended starting from 1 April 2021.

Air Quality Monitoring Data (1-hour)



Air Quality Monitoring Data (24-hour)



Remark:

Date

1) The existing air quality monitoring location AMS6 - Dragonair / CNAC (Group) Building (HKIA) was handed over to Airport Authority Hong Kong on 31 March 2021. 24-hr TSP monitoring at AMS6 was temporarily suspended starting from 1 April 2021.

Noise Monitoring Data


Project	Works	Date (yyyy-mm-dd)	Station	Start Time	Wind Speed, m/s	1st set 5mins		2nd set 5mins		3rd set 5mins		4th set 5mins		5th set 5mins		6th set 5mins		Overall (30mins)*		Unit
HKLR	HY/2011/03	2022-02-11	NMS5	09:59	<5	Leq:	54.2	Leq:	54.6	Leq:	55.6	Leq:	55.9	Leq:	53.9	Leq:	54.4	Leq:	58	dB(A)
						L10:	55.5	L10:	55.5	L10:	56.5	L10:	55.0	L10:	55.5	L10:	59			
						L90:	51.5	L90:	52.0	L90:	51.5	L90:	51.0	L90:	51.5	L90:	52.0	L90:	55	
HKLR	HY/2011/03	2022-02-16	NMS5	09:07	<5	Leq:	54.1	Leq:	54.9	Leq:	53.6	Leq:	55.0	Leq:	54.2	Leq:	54.7	Leq:	57	dB(A)
						L10:	55.5	L10:	57.0	L10:	55.0	L10:	56.5	L10:	55.5	L10:	56.0	L10:	59	
						L90:	51.0	L90:	51.5	L90:	51.0	L90:	51.5	L90:	51.5	L90:	51.5	L90:	54	
HKLR	HY/2011/03	2022-02-24	NMS5	13:33	<5	Leq:	57.2	Leq:	55.1	Leq:	56.3	Leq:	55.4	Leq:	58.2	Leq:	55.3	Leq:	59	dB(A)
						L10:	57.0	L10:	56.5	L10:	58.5	L10:	57.0	L10:	62.0	L10:	57.5	L10:	62	
						L90:	51.0	L90:	51.5	L90:	52.5	L90:	51.5	L90:	52.0	L90:	52.0	L90:	55	
HKLR	HY/2011/03	2022-02-28	NMS5	09:58	<5	Leq:	50.6	Leq:	50.9	Leq:	52.0	Leq:	52.5	Leq:	49.2	Leq:	51.0	Leq:	54	dB(A)
						L10:	52.0	L10:	53.0	L10:	54.0	L10:	55.0	L10:	49.5	L10:	53.0	L10:	56	
						L90:	47.0	L90:	48.0	L90:	48.5	L90:	47.5	L90:	46.5	L90:	48.0	L90:	51	

Remarks:

(1)* A facade correction of +3 dB(A) was applied to the measured noise level.

(2) Due to bad weather condition on 22 February 2022, noise monitoring at NMS5 was rescheduled from 22 February 2022 to 24 February 2022.

Graphical Plot of Noise Levels at NMS5



Remarks:

(1) A facade correction of +3 dB(A) was applied to the measured noise level.

(2) Due to bad weather condition on 22 February 2022, noise monitoring at NMS5 was rescheduled from 22 February 2022 to 24 February 2022.