



FOR CONTINUATION SEE FIGURE 3.5B

North Lantau Fault Zone Area Subparallel To An Inferred/Consealed Fault

Legend:

- Fill
 - Marine Deposits
 - Estuarine Deposits
 - Alluvium
 - Colluvium
 - Completely To Highly Decomposed Rock
 - Grade III Or Better Rock (Refer To Granite, Otherwise Indicated On Section)
 - F - Inferred Fault From Geophysical Data/Borehole Information
 - Inferred Rockhead Along Original Alignment
 - Inferred Rockhead Along Recommended Alignment
- ← Current Drillhole
 - ← Existing Drillhole
 - M - Marine Deposit
 - 1 Clay
 - 2 Silt
 - 3 Sand
 - A - Alluvial Deposit
 - V - Completely Decomposed Rocks
 - IV - Highly Decomposed Rocks
 - III - Moderately Decomposed Rocks
 - II - Slightly Decomposed Rocks
 - ₂₀ - SPT N Value

SCALE:
 V: 1 : 2000 @ A3
 H: 1 : 10000 @ A3

Note:
 Rockhead Level & Material Profiles Are Referred From Adjacent Drillholes & Geophysical Survey Results

AGREEMENT NO. CE 52/2007(HY)
 TUEN MUN - CHEK LAP KOK LINK - INVESTIGATION

GEOLOGICAL SECTION

SHEET 1 OF 3

SCALE	AS SHOWN	DATE	APR. 2009
CHECK	---	DRAWN	CL
JOB No.	60044963	DRAWING No.	Fig 2.5a
		REV	---